



The recommended torque value for the Multi-Unit main abutment is 30 Ncm. The recommended torque value for the upper connection screw is 15 Ncm.